




ARTIST PROOF COLLECTIVE

BASIC EMBROIDERY SPECIFICATIONS

EMBROIDERY COLUMNS

SPECIFICATIONS
Are for reference only...
THE CONCEPT HERE IS:
Embroidery is made up of threads, stitching into material to make an image. By following some basic stitching guidelines, the final product should be improved.


A COMPLEX, LARGER IMAGE REQUIRES MORE STITCHES AND ADDS A HIGHER COST—SIMPLIFYING/RESIZING AN IMAGE WILL DIMINISH STITCHES, AND SAVE YOU MONEY!



If an embroidery fill stitch can be eliminated and let the cap or garment show through, there will be fewer stitches and perhaps a lower price. (The final product will look similar, but will save stitches and money)



Use these tools against your image, to see if it complies with specs



MAX MINIMUM PATCH BORDER TOOL 3mm

MINIMUM SATIN COLUMN TOOL 1mm

TEXT .25
MINIMUM FONT SIZE TOOL

**IDEAL EMBROIDERY SIZE:
GARMENT LEFT CHEST
89mm W X 51mm H
(3.5 IN W X 2.0 IN H)**

**MAXIMUM EMBROIDERY SIZE:
CAP CENTER FRONT 120mm W X 60mm H (4.72 IN W X 2.17 IN H)
GARMENT LEFT CHEST 100mm W X 100mm H (4.0 IN W X 4.0 IN H)**

MINIMUM SIZE TRADEMARK .156" W
MINIMUM SIZE REGISTRATION MARK .125" W
TM ®